

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	L1	15973	(driver transmit\$4) same (output\$1 near2 buffer\$3)	US- PGPUB; USPAT	2005/03/03 15:50		
2	BRS	L2	4451	programmabl\$1 near3 delay\$2	US- PGPUB; USPAT	2005/03/03 15:52		
3	BRS	L3	213	1 and 2	US- PGPUB; USPAT	2005/03/03 15:52		
4	BRS	L4	189	simultaneously adj switch\$3 adj3 output\$1	US- PGPUB; USPAT	2005/03/03 15:53		
5	BRS	L5	1	3 and 4	US- PGPUB; USPAT	2005/03/03 16:03		
6	BRS	L6	2832	(rapid fast) near3 change near5 (current voltage)	US- PGPUB; USPAT	2005/03/03 16:04		
7	BRS	L7	6	4 and 6	US- PGPUB; USPAT	2005/03/03 16:26		
8	BRS	L8	123	3 and (ring\$3 noise)	US- PGPUB; USPAT	2005/03/03 16:27		
9	BRS	L9	4	6 and 8	US- PGPUB; USPAT	2005/03/03 16:51		
10	BRS	L10	3920	offset\$4 near3 switch\$3	US- PGPUB; USPAT	2005/03/03 16:52		
11	BRS	L11	4	3 and 10	US- PGPUB; USPAT	2005/03/03 16:59		
12	BRS	L12	1552	713/400.ccls. 713/401.ccls. 713/503.ccls.	US- PGPUB; USPAT	2005/03/03 17:00		
13	BRS	L13	9	3 and 12	US- PGPUB; USPAT	2005/03/03 17:00		
14	BRS	L14	8	13 not (7 or 9 or 11)	US- PGPUB; USPAT	2005/03/03 17:01		